



Product Change Notice: #VE20211106

Date: June 11, 2021

RE: End of Life for the M-FIAM7 Parts

To Our Valued Customer:

We appreciate your use of Vicor products. The purpose of this notice is to make you aware that the below parts will be discontinued.

Parts Affected	Suggested Alternative
M-FIAM7H11	M-FIAM7BH11
M-FIAM7H12	M-FIAM7BH12
M-FIAM7H21	M-FIAM7BH21
M-FIAM7H22	M-FIAM7BH22
M-FIAM7H23	M-FIAM7BH23
M-FIAM7HG1	M-FIAM7BHG1
M-FIAM7HG2	Contact Factory
M-FIAM7HG3	Contact Factory
M-FIAM7HN1	Contact Factory
M-FIAM7HN2	M-FIAM7BHN2
M-FIAM7HS1	M-FIAM7BHS1
M-FIAM7HS3	Contact Factory
M-FIAM7M11	M-FIAM7BM11
M-FIAM7M12	Contact Factory
M-FIAM7M13	Contact Factory
M-FIAM7M21	M-FIAM7BM21
M-FIAM7M22	M-FIAM7BM22
M-FIAM7M23	M-FIAM7BM23
M-FIAM7MG1	M-FIAM7BMG1
M-FIAM7MG2	Contact Factory
M-FIAM7MK1	Contact Factory
M-FIAM7MN1	M-FIAM7BMN1
M-FIAM7MN2	Contact Factory
M-FIAM7MN3	M-FIAM7BMN3
M-FIAM7MS1	M-FIAM7BMS1
M-FIAM7MS2	Contact Factory

Reason for the change:

The parts listed above are being discontinued due to a component obsolescence.

Recommended replacements:

The recommended replacement is the M-FIAM7B, which is in the same mechanical package and has equivalent electrical specifications, although system requalification may be necessary.

Schedule:

Due to limited supply of the component, there is very limited ability to accept any last time buy orders. Customers are urged to convert to the M-FIAM7B alternative as soon as possible.

Actions Required:

Customers should make note of the change and contact Applications Engineering with any questions.

Company contact for technical questions:

Applications Engineering Vicor Corporation

Ph: (978) 470-2900

email: apps@vicorpower.com